


Company Profile

# PT Karya Baru Rima.

Komp. PT. Pinang Jaya No.8, Jalan Yos Sudarso Batu Ampar,  
Batam Indonesia 29454 - [www.kbr-ropeaccess.com](http://www.kbr-ropeaccess.com)





# About Us



PT. Karya Baru Rima (KBR) has been established since 2005 located at Batam - Indonesia starting with CV. Karya Baru Rima and later on became PT. Karya Baru Rima on May 2013 which we decided to fully focus on Industrial Rope Access Service.

PT. Karya Baru Rima (KBR) managed by a team of professionals, leaders & staff which had experienced in Industrial Rope Access for Oil & Gas Industry, Marine, Construction, etc.

PT. Karya Baru Rima (KBR) have earned reputation to deliver services that meet our clients requirements. PT. Karya Baru Rima (KBR) became an IRATA full member for Operator & Trainer since 2014 with IRATA number 3043/OT

# Vision and Mission



To maintain highest service standard and deliver the right solutions.



To deliver our IRATA training to the highest industry standard




To make the spirit of corporate purpose evident to every customer that we have the opportunity to serve.



# Our Policy

We are committed to ensuring all work activities to be carried out safely, and with all possible measures taken to remove or to reduce the risks to the Health, Safety, Environment and Welfare of Workers, Contractors, Clients and anyone else who may be affected by our operations.





# About IRATA



IRATA is an acronym for the Industrial Rope Access Trade Association, that was formed in the UK in the late 1980's, to solve maintenance challenges in the offshore oil and gas industry. Its formation was the result of an initiative of a number of leading companies, who had begun to use industrial rope access techniques, to provide a safe working environment for the industry

The rope access technique developed by IRATA is used in a wide range of repair, maintenance, inspection and access work. Rope access methodology boasts an unrivalled safety record, short set-up and dismantling time, positive environmental benefits and removes the need for invasive access equipment or disruption to a worksite. We are extremely proud that the IRATA system of rope access continues to enjoy increasing popularity throughout the world.

IRATA is now recognized as the world's leading authority on industrial rope access. It has over 700 member companies around the world and has trained in excess of 130,000 rope access Technicians worldwide. IRATA directs and regulates, through its members, the training of all workers seeking its qualifications. These member companies provide training, operational services, or both.

# Our Services

## Service 1



Industrial Rope Access Training Certified by IRATA International

Since 2013-2024, We have trained more than 1000 candidates from Indonesia, Malaysia, Singapore, Philippine, Germany, Middle East & South Africa



## Service 2



NDT Inspection with Rope Access Technique



# Our Services

## Service 3



Blasting & Painting with  
Rope Access Technique



## Service 4



Derrick Survey, Derrick  
Building & Maintenance





Service 5

Rope Access Equipment  
Supply & Rental



Service 6

DROPS  
Survey



Our  
Services

# Project Documentation





# Project Documentation



# Our Portfolio

- 1 NDT & Load Test Inspection with RAT-PT. Rigspek Perkasa, Batam
- 2 Jack Up Rig Maintenance, Repair & NDT with RAT- Rig Resources Pte. Ltd, Location: Bahrain, Dubai, Singapore, Malaysia & Vietnam
- 3 NDT & Load Test Inspection with RAT - PT. Rigspek Perkasa, Batam
- 4 NDT & Load Test Inspection with RAT - PT. Rigspek Perkasa, Offshore
- 5 Mechanical Installation Service on Derrick with RAT, PT. Citra Tubindo Engineering, Batam
- 6 Tubing Installation on Derrick with RAT - Gas Oil Pte Ltd, Batam
- 7 NDT & Load Test Inspection with RAT on PRA 9 & PRA 15,PT. Safetech Indonesia, Sumatra
- 8 Blasting & Painting with RAT - Semen Padang, Batam
- 9 Mechanical Installation Service with RAT on Jangkrik FPU, SPIE Oil & Gas Services Indonesia, Karimun
- 10 NDT & Load Test Inspection with RAT - PT. Rigspek Perkasa, Batam





# Our Portfolio

- 11 CROPS Survey with RAT on PRA 15-PT. Safetech Indonesia, Sumatra
- 12 CROPS Survey with RAT on PRA 9-PT. Safetech Indonesia, Sumatra
- 13 Lifting Gear Inspection with RAT on PRA 15-PT. Safetech Indonesia, Sumatra
- 14 NDT Inspection with RAT, Premier Oil - Surveyor Indonesia, Natuna
- 15 NDT Inspection with RAT, Petronas Carigali - Surveyor Indonesia - Ketapang, Kepodang & Bukit Tua Field
- 16 NDT Inspection with RAT, Mubadala Petroleum - Surveyor Indonesia, Kalimantan
- 17 NDT Inspection with RAT, Premier Oil - Surveyor Indonesia, Natuna
- 18 NDT Inspection with RAT, Petronas Carigali - Surveyor Indonesia - Ketapang, Kepodang & Bukit Tua Field
- 19 NDT Inspection with RAT, Mubadala Petroleum - Surveyor Indonesia, Kalimantan
- 20 Painting with RAT, Exxon Mobil Cepu Limited, PT SPIE Oil & Gas Services Indonesia
- 21 NDT Inspection with RAT, RIG RAISIS, Radiant utama Interinsco Tbk.

# Current Project

- 1 NDT Inspection with RAT, PHKT-Radiant Utama Interinsco, Tbk
- 2 NDT Inspection with RAT, Medco E&P Tomori CRP Senoro, Radiant Utama Interinsco Tbk
- 3 Holiday Test with RAT, SOFIA OFFSHORE WIND FARM, - Seatrium
- 4 Painting Project with Rope Access , Offshore Construction Vessel DLV 2000-MCDERMOTT,BATAM



# Our Clients & Partner



# Our Clients & Partner



# Our Certification

## Certificate of Registration



This is to certify that Quality Management System of

**PT. KARYA BARU RIMA**

Komp. PT. Pinang Jaya No. 8, Jalan Yos Sudarso Batu Ampar, Batam- Indonesia

is in accordance with the requirements of the following standard

**ISO 9001:2015**

(Quality Management System)

### SCOPE

Wholesale Trade of Goods, Industrial Rope Access Services,  
Variety of Inspection (NDT, Painting, Lifting Equipment) &  
Other Specialized Construction Activities

Certificate Number : 131023016207

(IAF Code: 28,29,34)

Initial Registration Date : 13-Oct-2023  
1<sup>st</sup> Surveillance Date : 13-Sep-2024  
2<sup>nd</sup> Surveillance Date : 13-Sep-2025  
Certificate Expiry Date : 12-Oct-2026

**To verify certificate, visit at :**

[www.arscert.com](http://www.arscert.com)  
<https://uafaccreditation.org>  
<https://www.iafcertsearch.org/>

Issued by ARS Assessment Private Limited

*AB*  
Managing Director



UAF Address : 400, North Center Dr, STE 202, Norfolk, VA 23502, United States of America :

This certificate remains the property of ARS and must be returned to ARS on Cancellation or Suspension of the certificate. Validity of the certificate is subject to successful completion of surveillance audits. Further clarification regarding the scope of this certificate and the applicability of standard may be obtained by consulting the Organization on info@arscert.com

## Certificate of Registration



This is to certify that Environmental Management System of

**PT. KARYA BARU RIMA**

Komp. PT. Pinang Jaya No. 8, Jalan Yos Sudarso Batu Ampar, Batam- Indonesia

is in accordance with the requirements of the following standard

**ISO 14001:2015**

(Environmental Management System)

### SCOPE

Wholesale Trade of Goods, Industrial Rope Access Services,  
Variety of Inspection (NDT, Painting, Lifting Equipment) &  
Other Specialized Construction Activities

Certificate Number : 131023026208

(IAF Code: 28,29,34)

Initial Registration Date : 13-Oct-2023  
1<sup>st</sup> Surveillance Date : 13-Sep-2024  
2<sup>nd</sup> Surveillance Date : 13-Sep-2025  
Certificate Expiry Date : 12-Oct-2026

**To verify certificate, visit at :**

[www.arscert.com](http://www.arscert.com)  
<https://uafaccreditation.org>  
<https://www.iafcertsearch.org/>

Issued by ARS Assessment Private Limited

*AB*  
Managing Director



UAF Address : 400, North Center Dr, STE 202, Norfolk, VA 23502, United States of America :

This certificate remains the property of ARS and must be returned to ARS on Cancellation or Suspension of the certificate. Validity of the certificate is subject to successful completion of surveillance audits. Further clarification regarding the scope of this certificate and the applicability of standard may be obtained by consulting the Organization on info@arscert.com

# Our Certification

**Certificate of Registration** 

This is to certify that Occupational Health and Safety Management System of

**PT. KARYA BARU RIMA**

Komp. PT. Pinang Jaya No. 8, Jalan Yos Sudarso Batu Ampar, Batam- Indonesia

is in accordance with the requirements of the following standard

**ISO 45001:2018**  
(Occupational Health and Safety Management System)

**SCOPE**


Wholesale Trade of Goods, Industrial Rope Access Services,  
Variety of Inspection (NDT, Painting, Lifting Equipment) &  
Other Specialized Construction Activities

Certificate Number : 131023036209 (IAF Code: 28,29,34)

Initial Registration Date : 13-Oct-2023  
1<sup>st</sup> Surveillance Date : 13-Sep-2024  
2<sup>nd</sup> Surveillance Date : 13-Sep-2025  
Certificate Expiry Date : 12-Oct-2026

**To verify certificate, visit at :**  
[www.arscert.com](http://www.arscert.com)  
[www.uafaccreditation.org](http://www.uafaccreditation.org)  
[www.iafcertsearch.org](http://www.iafcertsearch.org)

Issued by ARS Assessment Private Limited

  
Managing Director

UAF Address: 400, North Center Dr, STE 202, Norfolk, VA 23502, United States of America

This certificate remains the property of ARS and must be returned to ARS on Cancellation or Suspension of the certificate. Validity of the certificate is subject to successful completion of surveillance audits. Further clarification regarding the scope of this certificate and the applicability of standard may be obtained by consulting the Organization or info@arscert.com



This is to certify that

**PT Karya Baru Rima (KBR)**  
Komplek PT Pinang Jaya No 8 Jin, Yos Sudarso Batu Ampar (Sebelum Showroom Toyota), Batam, 29454, Indonesia

Membership No.: 3043/OT

is a

**FULL MEMBER  
(OPERATOR)**

of IRATA International and complies with the regulatory requirements and applicable policies of IRATA International

Membership validity should be verified at [www.irata.org](http://www.irata.org)

  
**Dr S Kondaveeti**  
Head of Quality, Audit and Certification

Originally Registered: 06 November 2013  
Last Certification Date: 10 January 2023  
Certification Expiry: 09 January 2026



This certificate remains the property of IRATA International and is bound by the provisions of the Articles of Association & Bye-Laws of IRATA International. Membership renewal is due annually for continued validity. This certificate is valid until expiry of the Certification Expiry date shown above. Contact IRATA International, 1st & 2nd Floor, Unit 5, Conquest Business Park, Airport, Park, Thimble Hill, UK, Tel: +44 (0)1235 754 600. (17-211942\_2016)

# Our Certification



Certificate Number 24-6458915-A  
Issue Date 02 August 2024  
Expiry Date 01 August 2027  
ABS Port Office Batam, Indonesia  
Company's Website kbr-ropeaccess.com

## CERTIFICATE OF Recognized Service Supplier

This is to certify that

**PT. KARYA BARU RIMA**

located at

KOMP. PT PINANG JAYA NO 08 KAMPUNG SERAYA, BATU AMPAR, BATAM,  
29454 INDONESIA

having been audited by ABS and having given a satisfactory practical demonstration of the service listed below, is recognized by ABS as a Service Supplier to provide services which ABS Surveyors may rely on to make decisions affecting classification or statutory surveys.

### ESP Hull Gauging

Attached Certificate Appendix provides specific scope of approval, authorized personnel, manufacturer authorizations, and subcontractors.

It is the responsibility of the Service Supplier to employ, train and qualify persons in the service provided. If the service requires approval from manufacturers, the Service Supplier is responsible to maintain contact with the manufacturer and maintain any service manuals up to date. Where required by the category of service, the Service Supplier shall provide valid evidence that it is authorized or licensed by the equipment manufacturer to service the makes and models of equipment for which approval is sought. If approval from the manufacturer is not attained, a surveyor must be present at time of survey to continue work. Alternatively, current written instructions from the flag state are to be obtained to continue work without the surveyor present. Service Suppliers must present photo identification, evidence of qualification and authorizations from manufacturers, as applicable, at the time of service.

The ABS office issuing this certificate is to be kept updated with changes to the management of the company, employees, equipment and models on the authorization list and any changes made.

  
Susilo, Nikolas Hendro, Surveyor



Certificate Number 24-6458915-B  
Issue Date 02 August 2024  
Expiry Date 01 August 2027  
ABS Port Office Batam, Indonesia  
Company's Website kbr-ropeaccess.com

## CERTIFICATE OF Recognized Service Supplier

This is to certify that

**PT. KARYA BARU RIMA**

located at

KOMP. PT PINANG JAYA NO 08 KAMPUNG SERAYA, BATU AMPAR, BATAM,  
29454 INDONESIA

having been audited by ABS and having given a satisfactory practical demonstration of the service listed below, is recognized by ABS as a Service Supplier to provide services which ABS Surveyors may rely on to make decisions affecting classification or statutory surveys.

### Remote Inspection Techniques as An Alternative Means for Close-up Survey of Ships and Mobile Offshore Units

Attached Certificate Appendix provides specific scope of approval, authorized personnel, manufacturer authorizations, and subcontractors.

It is the responsibility of the Service Supplier to employ, train and qualify persons in the service provided. If the service requires approval from manufacturers, the Service Supplier is responsible to maintain contact with the manufacturer and maintain any service manuals up to date. Where required by the category of service, the Service Supplier shall provide valid evidence that it is authorized or licensed by the equipment manufacturer to service the makes and models of equipment for which approval is sought. If approval from the manufacturer is not attained, a surveyor must be present at time of survey to continue work. Alternatively, current written instructions from the flag state are to be obtained to continue work without the surveyor present. Service Suppliers must present photo identification, evidence of qualification and authorizations from manufacturers, as applicable, at the time of service.

The ABS office issuing this certificate is to be kept updated with changes to the management of the company, employees, equipment and models on the authorization list and any changes made.

  
Susilo, Nikolas Hendro, Surveyor

# Contact Us

 **Email**

[admin@kbr-ropeaccess.com](mailto:admin@kbr-ropeaccess.com)

 **Instagram**

[kbr\\_ropeaccess](https://www.instagram.com/kbr_ropeaccess)

 **Tiktok**

[pt.karyabarurima](https://www.tiktok.com/@pt.karyabarurima)

 **Website**

[www.kbr-ropeaccess.com](http://www.kbr-ropeaccess.com)

 **Contact**

Juwita +627886852810

 **Facebook**

KBR Rope Access

 **LinkedIn**

PT. KARYA BARU RIMA

